


BMP Inspection  
EAST HEMPFIELD TOWNSHIP



**BMP Name/ID**  
BMP 500

**NPDES Permit No.**

**Property Address**

**Type**  
Dry Extended Detention Basin

**Inspection Date**  
08/29/24

**Time**  
9:00AM

**Investigator**  
Charity Hain

**Temperature**  
76 °F

**24 Hr Rainfall**

**48 Hr Rainfall**

**Weather**  
Sunny

## Overall

**Satisfactory?**

**Comments**

No comments

## Components

**Vegetation (Excellent)**

**Erosion (Excellent)**

**Basin Bottom (Excellent)**

**Bank Stability (Excellent)**

**Spillway (Excellent)**

**Inlet and Outlet Conditions (Excellent)**

**Sediment and Debris Accumulation (Excellent)**

**Invasive or Unwanted Growth? (Excellent)**

## Recommendations

1. Maintenance: Ensure that maintenance and inspections on the facility are completed on a monthly basis or after each rainfall event.

Prepared By  **CSDatum**

# Photo Log

Photo No. 1: 1.jpg



Photo No. 2: 2.jpg



Photo No. 3: 3.jpg

